

GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT

From:
Sri A.Srinivas,
Executive Engineer (R&B),
BHIMAVARAM

To:
The **Principal**,
Vasavi Ideal Public School,
D.No.4-5, Chintadepalli,
Tadepalligudem Mandal,
W.G.Dist.

Lr.No. 337/ JTO2/ Soundness Certificate/ 2026, Date.23.03.2026.

Sir,

Sub :- Buildings (R&B) Department, Bhimavaram - **Vasavi Ideal Public School, D.No.4-5, Chintadepalli, Tadepalligudem (M)- Soundness Certificate issued - Reg.**

Ref: - 1. Lr.No.Nil, Dt.21.02.2026, of the Principal **Vasavi Ideal Public School, D.No.4-5, Chintadepalli, Tadepalligudem (M).**

2. Lr.No.Soundness Certificate/SA/TPG/2025, Dt.13.03.2026 of the Dy. Executive Engineer (R&B) **Tadepalligudem**

With reference to the above, I furnish herewith the Structural Soundness Certificate of the school building of **Vasavi Ideal Public School, which is located in D.No.4-5, Chintadepalli, Tadepalligudem (M), W.G.Dt.,** inspected by the Deputy Executive Engineer (R&B) Sub-Division, Tadepalligudem. The building having of Ground floor, 1st and 2nd floors RCC roof is structurally sound as per visual observation and I here with furnish Structural Soundness Certificate for the building for the period from **12.03.2026 to 11.03.2027** for renewal purpose only.

Encl : Soundness Certificate.

Yours faithfully,


Executive Engineer(R&B)
Division :: Bhimavaram.

23/3/26

STRUCTURAL SOUNDNESS CERTIFICATE

This is to certify that Vasavi ideal public school , bearing Door No.4-5 Chinatadepalli, Tadepalligudem Mandal West Godavari District was inspected on 12.03.2026. The said Building consisting of Ground floor, I st floor and 2nd floor R.C.C roof slab was structurally sound as per visual observation for the period from 12.03.2026 to 11.03.2027 for one year and this certificate is issued for recognition and renewal purpose only .

Ref

12/3/26

Assistant Engineer (R&B)
Tadepalligudem

12/3/26

Dy.Executive Engineer (R&B)
Tadepalligudem

// Counter signed //

Executive Engineer (R&B)

Bhimavaram
23/3/26